

REPORT DO	CUMENTATIO	N PAGE	PAGE Form Approved OMB No. 0704-0188			
1a. REPORT SECURITY CLASSIFICATION Unclassified	1b. RESTRICTIV None	1b. RESTRICTIVE MARKINGS None				
2a. SECURITY CLASSIFICATION AUTHORITY	3. DISTRIBUTIO	3. DISTRIBUTION/AVAILABILITY OF REPORT				
	Approved for	Approved for public release; distribution unlimited.				
2b. DECLASSIFICATION/DOWNGRADING SC	7					
4. PERFORMING ORGANIZATION REPORT N No. 2467	5. MONITORING	5. MONITORING ORGANIZATION REPORT NUMBER(S)				
6a. NAME OF PERFORMING ORGANIZATION	7a. NAME OF MONITORING ORGANIZATION					
Belvoir RD&E Center		72. NAME OF MONTORING ORGANIZATION				
Materials, Fuels and Lubricants Dir.						
6c. ADDRESS (City, State, and ZIP Code) Chemistry Research Division		7b. ADDRESS (C	ity, State, and ZIP	Code)		
Fort Belvoir, VA 22060-5606					į	
8a. NAME OF FUNDING/SPONSORING ORGANIZATION	9. PROCUREME	NT INSTRUMENT	IDENTIFICA	TION NUMBER		
8c. ADDRESS (City, State, and ZIP Code)	l	10. SOURCE OF	10. SOURCE OF FUNDING NUMBERS			
		PROGRAM	PROJECT	TASK	WORK UNIT	
		ELEMENT NO.	NO.	NO.	ACCESSION NO.	
11. TITLE (Include Security Classification) Evaluation of Sealants and Cleaners fo 12. PERSONAL AUTHOR(S) Lance Nation, Donovan Harris, and Date 13a. TYPE OF REPORT 13b. TIME CO	rio A. Emeric	. DATE OF REPORT	Von Month Coul	15	PAGE COUNT	
	6 TO Feb 88	May 1988	(rear, Moriul, Day)	13.1	42	
16. SUPPLEMENTARY NOTATION	in					
17. COSATI CODES		S (Continue on revers				
FIELD GROUP SUB-GROUP	LACV-30, seala	ints, cleaners, solve	nts, corrosion, m	arine envir	onment . ITT	
10 ABSTRCT (Continue on severe if						
Research performed to find substitutes for cleaners and sealants currently used in the LACV-30. Based on the results, recommendations are made for sealants and cleaners which will withstand the LACV-30's marine environment. Report includes appendices of test procedures.						
20. DISTRIBUTION/AVAILABILITY OF ABSTRAC	r ·	21. ABST	RACT SECURITY	CLASSIFICA	TIÓN	
TINCLASSIFIED/UNLIMITED X SAME		USERS Uncla	assified			
22a. NAME OF RESPONSIBLE INDIVIDUAL Lance Nation			EPHONE (<i>Include i</i> -664-1127	Area Code)	22c. Office Symbol STRBE-VC	

PREFACE


In the fall of 1986, the Marine Division of the Logistics Support Directorate, Belvoir Research, Development and Engineering Center, formally requested the Center's Chemistry Research Division, Materials, Fuels, and Lubricants Directorate, to estimate the program cost of replacing sealants currently being used on the Lighter Air Cushion Vehicle, 30-ton payload (LACV-30). After first consulting with soldiers who perform the LACV-30 maintenance, and then conducting a physical survey of the craft, the following problems surfaced:

- Corrosion within the electrical system was the prime maintenance problem;
- Cleaning materials and procedures were inadequate;
- Abrasion resistance of the polysulfide base sealants was insufficient;
- Tack/cure time of the polysulfide base sealants was considered too long; and
- The sealants did not prevent corrosion of the cadmium plated bolts used on the craft.

After briefing the Directorate of Maintenance, US Army Troop Support Command (TROSCOM), St. Louis, MO, of the LACV-30's corrosion problems, the task of researching substitutes for those sealants and solvents presently in use commenced.

This report contains the research to improve the corrosion resistance and maintainability of the LACV-30 and other equipment exposed to a marine environment. The project was divided into six groups:

- Market Survey of Products
- Outdoor Exposure
- Indoor Exposure
- Tack/Cure Testing
- Cleaner Testing
- Data Analysis.



Analysis of these six groups resulted in recommending cleaners which would withstand the marine environment of the LACV-30.

TABLE OF CONTENTS

			Page
SE	CTION I	EXPERIMENTAL PROCEDURE	1
		Approach	1
		Tests Performed	1
SE	CTION II	TEST RESULTS	2
		Wet Assembly	2
		Faying Surfaces	2
		Polysulfide Solvents	2
		Cleaners	2
SE	CTION III	CONCLUSIONS	3
FI	GURES	-	
1	Polyurethane	Paints	4
2	Polyurethane	Caulk	5
3	Polysulfide Se	ealants (2 Components)	6
4	Polysulfide C	aulk (1 Component)	7
5	Translucent C	aulk	8
6	Miscellaneous	s Sealants	9, 10
7	Aerosol Paint	s	11
8	Thread Sealar	nts	12
9	Rust Preventiv	ves	13
10	Silicone Seale	ers	14-16
11	Bare Metal Bo	olts	17
12	PSS Results		18
13	Cleaners`		19, 20

Page

APPENDICES

A	Tack/Cure Time Test Procedure	21
В	Sealant Outdoor Test Procedure	22
C	Wet Assembly Sealant Test Procedure	23
D	Sealant Indoor Test Procedure	24
E	Wet Assembly Test Materials	25
F	Mating Surfaces Sealant Test Procedure	26
G	Polysulfide Solvent Test Procedure	28
Н	Cleaner Test Procedure	29
I	Supplemental Cleaner Test Information	31

SECTION I. EXPERIMENTAL PROCEDURE

APPROACH

A market survey was initially conducted for possible replacement of sealants presently being used in wet assembly and faying surfaces. A second market survey was conducted to find a replacement for the Methyl Ethyl Ketone (MEK) and polysulfide solvents presently in use. A third survey was conducted to find a biodegradable waterless or cold water detergent that could be used in the general wash down of the LACV-30.

The second phase of the program involved laboratory testing on products received from the market survey. The tests simulated the marine environment of the LACV-30.

The third phase of the program involved evaluating test results and making recommendations for replacement products to be used in the field.

TESTS PERFORMED

Sealants tested as replacements for the wet assembly underwent three test runs:

- 1. Tack/Cure Test (see Appendix A)
- 2. Outdoor Exposure (see Appendices B and C)
- 3. Indoor Exposure (see Appendices D and C)

Materials used and panel preparation of indoor and outdoor exposures are shown in Appendix E.

Sealants tested for use on faying surfaces underwent two test runs:

- 1. Tack/Cure Test (see Appendix A)
- 2. Mating Surface Test (see Appendix F)

The solvents considered as replacements for the polysulfide solvents were tested in accordance with the Polysulfide Solvent Test (see Appendix G). The commercial cleaners, in order to be considered, were tested as described in the Cleaner Test (see Appendix H).

SECTION II. TEST RESULTS

WET ASSEMBLY

From the observations of the test run and the data generated from all products (Figures 1-11), the top rated sealant based solely on corrosion resistance performance was number 4 of the commercial polyurethane caulks (Figure 2). After 21 weeks in the salt spray and 33 weeks outdoors, only slight corrosion was noticed on the area the sealant was protecting. Commercial sealants numbers 12, 13, 33, and 35 had the best tack/cure times with a 1 hour tack time and a 2 to 3 hour cure time.

FAYING SURFACES

From the observations and data gathered on this test for all sealants (Figures 1-10), commercial polyurethane caulk number 4 (Figure 2) was observed to be the most likely to protect a mating area in a marine environment. This caulk is the same product noticed to have the most favorable data for the Wet Assembly Test.

POLYSULFIDE SOLVENTS

From the two solvents tested (Figure 12), PSS-2 outperformed PSS-1 in two out of three tests. PSS-2 can be used as a year-around solvent, while PSS-1 is only effective in a certain temperature range.

CLEANERS

Of the commercial cleaners tested (Figure 13), the following are recognized as the top five: numbers 12, 11, 6, 5, and 9. These cleaners had a film removal of 75 percent and a remaining chlorine content of less than 1 percent.

SECTION III. CONCLUSIONS

- It is concluded from all testing and data that commercial sealant number 4 was the best overall sealant for both wet assembly and faying surfaces. As far as corrosion resistance, number 4 had the best results for both wet assembly and faying. This sealant also had an acceptable tack time of 1 hour and cure time of 10 hours. (Refer to Appendix I for additional cleaner test information).
- The polysulfide solvent data showed that PSS-2 (Figure 12) was the best polysulfide solvent for use on-board the LACV-30.
- Of the cleaners tested, the following five had favorable results: numbers 5, 6, 9, 11, and 12 (Figure 13). Out of these five, cleaner number 12 outperformed each of the other four cleaners.




Figure 1. Polyurethane Paints





Figure 2. Polyurethane Caulk

RECESSES PERFECTS PARTITION FOR STATE

CONTROL SALVERON CALIFORN PERSONAL NOVINSAN



公司不言以放 一一一一 持数其行

25.77.77.7

The second of th

NOTE: TACK/CURE AND FAYING TESTS NOT RUN BECAUSE PRODUCT CRACKS UNDER VIBRATION.

Figure 3. Polysulfide Sealants (2 Components)






Figure 4. Polysulfide Caulk (1 Component)



SLIGHT CORROSION
OUTDOORS
OUTDOORS
INDOOR HOURS
COMMERCIAL TACK CURE
10 1 15


Figure 5. Translucent Caulk

- MASSESS - MANNEY FROM PERSONAL PRINCIPAL FROM MANNEY PRINCIPAL RE-




INITIAL OUTDOORS [[[[[]]]] TERMINATED OUTDOORS	INDOOR HOURS	DATA. COMMERCIAL TACK CURE	10	1 3	IE TO 13 1 2	
INITIAL SALT SPRAY [[[[[]]]]] TERMINATED SALT SPRAY [[[]]] INIT	NOTES: FAYING AND TACK/CURE TESTS NOT RUN ON COMMERCIAL 10.	FAYING TEST NOT RUN ON COMMERCIAL 11 DUE TO SALT SPRAY DATA.	OUTDOOR AND FAYING TESTS NOT RUN ON COMMERCIAL 12 DUE TO	SALT SPRAY DATA.	FAYING AND TACK/CURE TESTS NOT RUN ON COMMERCIAL 13 DUE TO	SALT SPRAY AND OUTDOOR DATA.

Figure 6. Miscellaneous Sealants (1 of 2)



SALT SPRAY DATA. COMMERCIAL TACK DUTDOOR, FAYING, AND TACK/CURE TESTS NOT RUN ON COMMERCIAL 16 NOR 17 DUE TO SALT SPRAY DATA. 18 14 SUTDOOR AND FAYING TESTS NOT RUN ON COMMERCIAL 18 DUE TO ' FACK/CURE TEST DATA.	NOTES: FAYING AND TACK/CURE TESTS NOT RUN ON COMMERCIAL 15 DUE TO		INDOOR	NDOOR HOURS
N ON COMMERCIAL 18 DUE TO	A. G AND TACK/CLIRE TESTS NOT BLIN ON COMMERCIAL	COMMERCIAL	TACK	CURE
IR AND FAYING TESTS NOT RUN ON COMMERCIAL 18 DUE TO ' JRE TEST DATA.	7 DUE TO SALT SPRAY DATA.	81	14	96
JRE TEST DATA.	R AND FAYING TESTS NOT RUN ON COMMERCIAL 18 DUE TO			
	JRE TEST DATA.			


Figure 6. Miscellaneous Scalants - Continued (2 of 2)



NOTE: OUTDOOR, FAYING, AND TACK/CURE TESTS NOT RUN BECAUSE PRODUCTS WERE INCOMPATIBLE WITH DEGREASER.

Figure 7. Aerosol Paints

CONTRACT DESCRIPTION OF THE PROPERTY OF THE PR




INITIAL OUTDOORS TERMINATED OUTDOORS CURE INDOOR HOURS 25 AND 26 WERE NOT TACK-FREE AFTER 120 HOURS COMMERCIAL TACK OR CURED NOTES: OUTDOOR, FAYING, AND TACK/CURE TESTS NOT RUN ON COMMERCIAL 24 FAYING TEST NOT RUN ON COMMERCIAL 25 DUE TO TACK/CURE DATA. SALT SPRAY AND FAYING TESTS NOT RUN ON COMMERCIAL 26 DUE TERMINATED SALT SPRAY DUE TO SALT SPRAY. TO TACK/CURE DATA. INITIAL SALT SPRAY

Figure 8. Thread Scalants


KELLER LES

THE PHILLIPS LIGHTING PRINCES PRINCES PRINCES PRINCES NAMED AND PRINCES PRINCES PRINCES



SALT SPRAY, FAYING, AND TACK/CURE TESTS NOT RUN DUE TO OUTDOOR DATA. NOTE:

Figure 9. Rust Preventives




		NDC	INDOOR HOURS
NOTES: SALT SPRAY AND FAYING HOT TESTS NOT RUN ON COMMERCIAL 31 DUE TO	COMMERCIAL		TACK CHRF
OUTDOOR DATA			
OUTDOOR AND FAYING HOT TESTS NOT RUN ON COMMERCIAL 32 DUE TO	31	-	36
TACK/CURE DATA.	32	2	DOESN'T CURE
OUTDOOR AND FAYING TESTS NOT RUN ON COMMERCIAL 33 DUE TO	33	-	2
SALT SPRAY DATA.			

Figure 10. Silicone Sealers (1 of 3)


XXXXX

PRESENTED PROPERTY



INDOOR HOURS	TACK CURE	12 84	1 3	49 120
	COMMERCIAL	¥	35	36
	NOTES: FAYING TEST NOT RUN ON COMMERCIAL 34 DUE TO TACK/CURE DATA. FAYING TEST NOT RUN ON COMMERCIAL 35 DUE TO SALT SPRAY DATA.	SALT SPRAY AND FAYING TESTS NOT RUN ON COMMERCIAL 36 DUE TO	TACK/CURE DATA.	


Figure 10. Silicone Sealers - Continued (2 of 3)



一次の かかかかり

METHODS EAVING AND TACK CITIES TESTS NOT DITH ON COMMISSION 38
DUE TO SALT SPRAY. SALT SPRAY AND FAYING TESTS NOT RUN ON COMMERCIAL 39.

Figure 10. Silicone Sealers - Continued (3 of 3)



NOTE: OUTDOOR TEST NOT RUN ON 304 STAINLESS STEEL.

Figure 11. Bare Metal Bolts

Kittata Markets

HOURS OF MAX EFFECTIVENESS/PERCENTAGE LIFTED AT:

SOLVENT	35°F	65°F	95°F
PSS-1	No effect	3 hr/75%	No effect
PSS-2	1 hr/35%	1 hr/50%	1 hr/100%

Figure 12. Polysulfide Sealant Solvent (PSS) Results




Figure 13. Cleaners (1 of 2)

THE TRANSPORT OF THE PROPERTY OF THE PROPERTY




Figure 13. Cleaners - Continued (2 of 2)

APPENDIX A TACK/CURE TIME TEST PROCEDURE

- 1. Set cold box to 35°F.
- 2. Chill test panels overnight, clean with clean cloth and MEK.
- 3. Apply test materials per instruction sheet, and measure film thickness.
- 4. Check hourly over a 9-hour period to establish tack free time.
- 5. The following morning, check those systems not tack-free after 9 hours; if cured, set up to repeat test at end of day to see if tack-free time between 9 and 12 hours.
- 6. Once tack-free time established, check at 24-hour intervals to establish cure time. No uncured material found.
- 7. The tack-free state will be determined by gently pressing down on the film surface using a covered forefinger, and not forcing the film surface to break.
- 8. Determine the he cure time by using either a cake tester, sewing needle or scapel, in descending order of the coating thickness.
- 9. Apply all samples to the same thickness for all materials tested.
- 10. Prepare all panels in duplicate for tack/cure test.

APPENDIX B SEALANT OUTDOOR TEST PROCEDURE

- 1. Leave preconditioned, precorroded panels outdoors overnight and assemble (refer to Appendix C).
- 2. Spray twice a week with an acid marine solution (3.5%, pH 4.1).

- 3. Schedule bolt inspection at 3-week intervals. One bolt from each panel will be removed, inspected, cleaned, and then reassembled.
- 4. Inspect all panels weekly for any signs of corrosion which will be noted and tracked, but do not remove panels prior to the next scheduled removal date. For a given sealant
 - a. If up to three bolts show signs of corrosion in different panels, remove two bolts at the next scheduled period.
 - b. If four or more bolts show signs of corrosion in different panels, remove half at the next scheduled period, and half the following period.
 - c. If three or more bolts on a single panel show signs of corrosion, pull all the bolts on that panel at next regular period, and redo the entire panel, providing the other panels in that sealants' test set are relatively corrosion free.
 - d. Reporting periods are in 84-day segments from the start date of sealant application.

APPENDIX C WET ASSEMBLY SEALANT TEST PROCEDURE


Procedure

- 1. Using MEK and a clean, lint-free cloth, clean preconditioned, precorroded panels.
- 2. Completely coat bolts and A1 washers with sealant. Install all hardware per diagrams below and tighten finger-tight.
- 3. Snug up six bolts with teflon washers.
- 4. Torque down two bolts to 10 psi for broken film testing.
- 5. Cure and test per exposure instructions.

Diagram Wet Assembly Sealant

Test panels: precorroded Al 6061-T6

1 each - 4" x 6" panels $\frac{2 \text{ each - 4"}}{2 \text{ panels}} \times 3$ " panels 3 panels = panel set




Controls with Cd plated bolts MIL-S-81733

Panel Assembly Diagram

Four panel sets per exposure with front TFE washer slotted per sealant

Four panel sets per exposure with rear TFE washer slotted per sealant

Four panel sets per exposure of front and rear TFE washers slotted per sealant



RESERVED BROKEN FILM TESTING

Pattern for checking slotted teflon washers

APPENDIX D SEALANT INDOOR TEST PROCEDURE

- 1. Leave preconditioned, precorroded panels indoors overnight at 35-40°F and RH > 80%.
- 2. Clean and assemble (refer to Appendix C).
- 3. Cure at 35-40°F/RH \geq 80% for 24 hours.
- 4. Expose to cyclic salt fog test for 7 days, then wash down panels using tap water and a hose nozzle. Check for signs of corrosion, replace back into the salt spray, and expose for another 7 days; then, wash again.
- 5. Once cured score film for broken film testing.
- 6. Schedule bolt removal the same as the outdoor exposure, using the same bolt removal guidelines.
- 7. Salt Spray Test Cycle:

Spray 1 hour Purge 2 hours Soak 3 hours

Total T 6 hours (one cycle); four cycles/day

APPENDIX E WET ASSEMBLY TEST MATERIALS

Materials

Al 6061-T6 plates and washers

Cd plated carbon steel bolts and nuts

316 stainless steel bolts and nuts

303/304 stainless steel bolts and nuts

18-8 stainless steel bolts and nuts

MIL-S-81733 (Sealing and Coating Compound, Corrosion Inhibitive)

MIL-S-8802 (Sealing Compound, Temperature-Resistant, Integral Fuel Tanks and Fuel Cell Cavities, High-Adhesion)

Methyl Ethyl Ketone (MEK)

Commercial Marine Mix

Tap Water

MIL-C-83360C (Cleaning and Lubricating Compound, Electrical Cleaner).

Panel Preparation

- 1. Use precorroded panels.
- 2. Wash off precorroded panels with tap water, using a hose and nozzle. Pressure and stream to be determined.
- 3. In Room B119, air dry panels and store them in open racks to be used as needed.
- 4. For all testing: Immediately prior to applying a sealant, clean down the panels using a clean cloth wetted with MEK, air dry, and apply wipe in one direction only.

APPENDIX F MATING SURFACES SEALANT TEST PROCEDURE

1. COMMON. MITT-2-0005	1.	Controls:	MIL-S-8802
------------------------	----	-----------	------------

2. Materials:

- a. 12 panels per spreadable sealant
- b. 12 panels per dry sealant
- c. 8 bolts per panel
- d. 2 face plates per panel
- 3. Apply the spreadable sealants to cover the area from the inner diameter of the center hole to the outer diameter of the cover plates.
- 4. For the tape type sealants, assemble six panels by placing a single line of tape so that all the bolt holes are inside the tape circle, and the top circle lies well within the cover plate's circumference. Assemble the six panels so that the plates' bolt holes lie between two lines of tape.
- 5. Dip the aluminum in primer at the time of assembly; therefore, they must be chromated in advance, per MIL-C-5541.
- 6. Expose six panels of the spreadable sealants and all six tape sealants to 140°F for 7 days, cool to room temperature, then chill to 20°F for 48 hours before going into a cyclic salt spray. After one week, wash down with marine mix. Salt spray test cycle:

Salt Spray 1 hour Purge 2 hours Soak 3 hours

Cure the other six sealant panels at 35-40°F, RH \geq 80%. Chill 24 hours to -20°F for 48 hours before going into the cyclic salt spray. After one week, wash down with marine mix.

7. Every 4 weeks, remove the bolts from one panel of each of the two treatments per sealant, and remove one cover; then, reseal as required.

NOTE: Any given cover will be removed only once every 24 weeks.

- 8. At the time of each 4-week inspection, document the following:
 - a. Ease of removing cover plate
 - b. Ease of removing old sealant, if required
 - c. Ease of applying new sealant
 - d. Ease of resealing unit
 - e. All signs of corrosion
- 9. Check weekly for signs of corrosion or film failure by placing in bucket of tap water and looking for air bubbles.
- 10. Reporting periods are in 84-day segments from the start date of sealant application.

APPENDIX G POLYSULFIDE SOLVENT TEST PROCEDURE

1.	Materials:
4.	wateriars.

- a. Three polysulfide solvents
- b. MIL-S-81733 A&B
- c. MIL-S-8802 A&B
- c. AMS-2267
- 2. Elapsed time for solvent to lift sealant at 75°F:
 - a. Use bolts with sealant on them.
 - b. Make panels with fillets of sealant on them.
 - c. Check hourly over a 9-hour period.
- 3. Elapsed time for solvent to lift sealant at 55°F:
 - a. Bolts with sealants.
 - b. Panels with fillets of sealants.
 - c. Check hourly over a 9-hour period.
- 4. Elapsed time for solvent to lift sealant at 35°F:
 - a. Bolts with sealants.
 - b. Panels with fillets of sealants.
 - c. Check hourly over a 9-hour period.

APPENDIX H CLEANER TEST PROCEDURE

-	_	•	^-	
1	Precorro	NOIDE	At Thect	Danale
1.	LICCUIL		OI ICSL	I dilcis

- a. Materials
 - (1) Al 6061-T6
 - (2) Coarse grit blasted surfaces
 - (3) $3'' \times 3'' \times \frac{1}{8}''$ panels
- b. Salt Spray Marine Kesternich Cabinet
 - (1) 30-day exposure
 - (2) Spray cycle:

8 hrs	Salt Spray	Mon-Fri
16 hrs	Hot Soak (95°F-95%RH)	Mon-Fri
64 hrs	Hot Soak (95°F-95%RH)	Fri-Mon

- (3) Spray with Fuel and Hydraulic Fluid Mixture
- (4) Air Dry and Store
- c. Control Several panels will be exposed using the cyclic salt spray to determine relative surface chlorides before cleaning.

2. Test Materials Cleaner Test

- a. Control
 - (1) Methyl Ethyl Ketone (MEK)
 - (2) Clean, lintless cloth
 - (3) Wipe down panel face
- b. Test Materials, non-etchant
 - (1) Test Solvent
 - (2) Clean, lintless cloth
 - (3) Wipe down panel face

- c. Test Materials, etchant
 - (1) Test Solvent
 - (2) Beaker
 - (3) Immerse panel lift out allow to work per data sheet
 - (4) Clean off per data sheet
- d. Hot Spray Cleaners
 - (1) Use car spray wand.
 - (2) Use hot water tap
 - (3) Spray and revise per data sheet
- e. Test Conditions
 - (1) Chill panels to 20°F (four panels per cleaner) overnight.
 - (2) Chill to a volume of the test solution to 20°F, except for the hot spray cleaners or if counterindicated by the product data sheet; then, use 40°F solvent temperature.
 - (3) All test specimens will be cured in a low temperature, high humidity environment.
 - (4) Clean two chilled panels using the chilled cleanser.

NOTE: Do not remove panels from cold box until ready for test.

- (5) Clean the other chilled panel using room temperature solvent.
- (6) Use insulated rubber gloves.
- f. Specimen Examination
 - (1) Check to see if petroleum film and hydraulic fluid film removed; if yes, then
 - (2) Perform elemental analysis in scanning electron microscope (SEM) at 40X, 10 kilovolts, using no standards program, NOSTD.

NOTE: Prior to SEM analysis, place sample in a vacuum oven (120°F).

APPENDIX I SUPPLEMENTAL CLEANER TEST INFORMATION

- 1. The self-locking nuts used to secure the bolts have the following two inherent problems which were not discovered until all tests were already in progress:
 - a. Almost all the nuts are located in areas which are not accessible using only the human arm.
 - b. The nuts remove all the sealant on the bolt threads.
- 2. The requirements generated by the problems of the self-locking nuts are:
 - a. Any sealant must be able to be applied using a spray wand.
 - b. The cadmium plating should be replaced by a more marine resistant coating or the bolt material changed to a more corrosion resistant metal.
- 3. There has been no documentation of any type as to the rate of bolt failure, rate of bolt replacement, nor have any samples of used bolts been supplied for evaluation. It is therefore not possible to weigh and evaluate the possible trade offs between meeting the purely technical requirements of the sealants, and meeting the user's requirements.

DISTRIBUTION FOR REPORT NO. 2467

DEPARTMENT OF DEFENSE

- Director, Technical Information
 Defense Advanced Research Projects
 Agency
 1400 Wilson Blvd.
 Arlington, VA 22209
- 1 Director
 Defense Nuclear Agency
 ATTN: TITL
 Washington, DC 20305
- Defense Technical Information Center
 Cameron Station
 ATTN: DTIC-FDAC
 Alexandria, VA 22304-6145

DEPARTMENT OF THE ARMY

- 1 HQDA (DAMA-AOA-M) Washington, DC 20310
- 1 HQDA (DALO-SMT) Washington, DC 20310
- 1 HQDA (DAEN-RDL) Washington, DC 20314
- 1 HQDA (DAEN-MPE-T) Washington, DC 20314
- 1 Commander US Army Missile Research & Development Command ATTN: AMSMI-PR Redstone Arsenal, AL 35809
- Director
 Army Materials and Mechanics Research
 Center
 ATTN: AMXMR-RL Technical Library
 Watertown, MA 02172-0001

- Commander
 Chemical Research R&D Center
 ATTN: SMCCR-SPS (Tech Library)
 Aberdeen Proving Ground, MD 21005
- Commander
 US Army Aberdeen Proving Ground
 ATTN: STEAP-MT-U (GE Branch)
 Aberdeen Proving Ground, MD 21005
- Director
 US Ballistics Research Laboratory
 ATTN: AMXBR-OD-ST (STINFO)
 Aberdeen Proving Ground, MD 21005-5066
- Director
 US Army Engineer Waterways Experiment
 Station
 ATTN: Chief, Library Branch
 Technical Information Center
 Vicksburg, MS 39180
- 1 Commander US Army Armament Research & Development Command * ATTN: SMCAR-TSS Dover, NJ 07801-5001
- Commander
 US Army Troop Support & Aviation
 Materiel Readiness Command
 ATTN: DRSTS-MES (1)
 4300 Goodfellow Blvd.
 St. Louis, MO 63120
- Director
 Petrol & Fld Svc Dept
 US Army Quartermaster School
 Fort Lee, VA 23801
- 1 US Army Tank Automotive Command ATTN: DRSTA-TSL Warren, MI 48090

- US Army Laboratory Command ATTN: M. Levy SLCMT-MN Materials Technology Laboratory Watertown, MA 02172-0001
- US Army Laboratory Command ATTN: J. Wells SLCMT-MCZ Materials Technology Laboratory Watertown, MA 02172-0001
- 1 Commander US Army Electronics Research & Development Command ATTN: DELSD-L Fort Monmouth, NJ 07703-5301
- 1 President
 US Army Aviation Test Board
 ATTN: STEBG-PO
 Fort Rucker, AL 36360
- US Army Aviation School Library PO Drawer O
 Fort Rucker, AL 36360
- 1 HQ 193D Infantry Brigade (Panama)ATTN: AFZU-FEAPO Miami 34004
- Special Forces Detachment, Europe ATTN: PBO APO New York 09050
- Engineer Representative
 USA Research & Standardization Group
 (Europe)
 Box 65
 FPO 09510

ቜቔ፟፝ቝ፟ቜቔቔቜቜኯ፠ቒ፟ኇ፞ቒጜ፞ፙጜፙጜፙጜፙጜዄጜዄጜዄጜዄጜፙጜዀዀዀዀዀጜዹጜጜፙጜፙጜጜጜጜዄጜዄጜዄጜዄጜዄጜዄ

1 Commander
Rock Island Arsenal
ATTN: SARRI-LPL
Rock Island, IL 61299-7300

- HQDA
 ODCSLOG
 DALO-TSE
 Room 1E588, Pentagon
 Washington, DC 20310-0561
- Plastics Technical Evaluation Center ARRADCOM, Bldg 3401 Dover, NJ 07801
- Commandant
 US Army Engineer School
 ATZA-CDD
 Fort Belvoir, VA 22060
- 1 US Army AMCCOM ATTN: Joseph Menke 1032 N. Thornwood Davenport, IA 52804
- Commander
 Headquarters, 39th Engineer Bn (Cbt)
 Fort Devens, MA 01433
- 1 President US Army Airborne, Communications & Electronics ATTN: STEBF-ABTD Fort Bragg, NC 28307
- 1 President
 US Army Armor and Engineer Board
 ATTN: ATZK-AE-PD-E
 Fort Knox, KY 40121-5470
- 1 Director ATTN: STSTO-TPP Tobyhanna Army Depot Tobyhanna, PA 18466-5097
- Commander and Director USA FESA ATTN: FESA-TS Fort Belvoir, VA 22060

- 1 HQ, USAEUR & Seventh Army Deputy Chief of Staff, Engineer ATTN: AEAEN-MT-P APO New York 09403
- Director
 US Army TRADOC
 Systems Analysis Activity
 ATTN: ATAA-SL (Tech Lib)
 White Sands Missile Range, NM 88002

BELVOIR RD&E CENTER

- 1 Commander STRBE-Z
- 1 Deputy Commander STRBE-ZD
- 1 Technical Director STRBE-ZT
- 1 Assoc Tech Dir (E&A) STRBE-ZTE
- 1 Assoc Tech Dir (R&D) STRBE-ZTR
- 1 Executive Officer STRBE-ZX
- 1 Sergeant Major STRBE-ZM
- 1 Advanced Systems Concept Dir STRBE-H
- 1 Program Planning Div STRBE-HP
- 1 Foreign Intelligence Div STRBE-HF
- 1 Systems and Concepts Div STRBE-HC
- 4 STRBE-V
- 20 STRBE-VC
- 3 Tech Reports Ofc STRBE-BPG
- 3 Security Ofc (for liaison officers) STRBE-S
- 2 Tech Lib STRBE-BT
- 1 Public Affairs Ofc STRBE-I
- 1 Ofc of Chief Counsel STRBE-L

DEPARTMENT OF THE NAVY

- Director
 Physics Program (421)
 Office of Naval Research
 Arlington, VA 22217
- 2 Commander
 Naval Facilities Engineering Command
 Department of the Navy
 ATTN: Code 032-B
 062
 200 Stovall Street
 Alexandria, VA 22332

- US Naval Oceanographic Office Navy Library/NSTL Station Bay St. Louis, MO 39522
- Library (Code L08A)
 Civil Engineering Laboratory
 Naval Construction Battalion Center
 Port Hueneme. CA 93043
- Director
 Earth Physics Program
 Code 464
 Office of Naval Research
 Arlington, VA 22217
- Naval Training Equipment Center ATTN: Technical Library Orlando, FL 32813
- 3 Naval Sea Systems Command ATTN: P. Schneider PMS377J1 Washington, DC 20362-5101
- Naval Air Development Center ATTN: V. S. Agarwala, Code 6062 Warminster, PA 18974
- 3 David W. Taylor Naval Research Center ATTN: A. G. S. Morton Code 2813 Annapolis, MD 21402

DEPARTMENT OF THE AIR FORCE

- HQ USAF/RDPT ATTN: Commander Washington, DC 20330
- 1 HQ USAF/PREEU Chief, Utilities Branch Washington, DC 20330
- HQ Air Force Engineering & Services Ctr Technical Library FL7050 Tyndall AFB, FL 32403

- 1 US Air Force
 Warner Robins Air Logistics Center
 WR-ALC/MMEM
 Warner-Robins AFB, GA 31098
- 1 Chief, Lubrications Branch Fuels & Lubrications Div ATTN: AFWAL/POSL Wright-Patterson AFB, OH 45433

END 1)ATE FILMED 9- F8 DTIC